

## ERRATA SHEET

---

Revision 1.0 2006-04-13

### VoIP Phone snom 300

#### **1. Ethernet cable interference in case the cable shielding is defective**

##### **Description**

**If the Ethernet cable shielding (in case shielding is present) is lose (defective), the display may in some cases show problems.**

**Serial number: 000413250040 – 000413252750**

##### **Workaround**

**Restart the phone.**

##### **Planned fixes**

**Next hardware revision.**